



Pre-Inspection Checklist Sub Structure Block Work to FFL	
<b>Project:</b> Taylor Wimpey North Finchley Site	<b>Date:</b> 26 March 2025
<b>Area:</b> Block T4	<b>Am / Pm:</b> AM
<b>Locaton:</b> Block T4	<b>Drawing Number:</b> 22227-BM3-T4T5-L0-DR-A-150 C2
<b>Weather Condition:</b> Fine / mild	<b>Sheet Number:</b> -

Table of Contents

- Setting Out Line & Level to Current Drawings
- Product Material Compliant With Engineers/Architect Specification
- Specified Bedding Depth, Colour & Mlxing Ratio to Specification
- Specified DPC Installed & at Correct Level
- Specified Wall Ties & Air Vents Installed at Correct Location & Height
- DPC / Membrane Installed as Per Specification
- Brick Type
- Lintel Bearing

Completed By: LP

Date Completed: 26 March 2025





Completed By: LP

Date Completed: 26 March 2025





Completed By: LP

Date Completed: 26 March 2025





Specified DPC Installed & at Correct Level

**Completed By:** LP

**Date Completed:** 08 April 2025



Completed By: LP

Date Completed: 26 March 2025





**Completed By:** LP  
**Date Completed:** 08 April 2025



Completed By: LP

Date Completed: 27 March 2025





Completed By: LP

Date Completed: 27 March 2025





Proceed/not proceed

Reason for Rejection/Comments: All the sub structure block work has been inspected by NHBC

Signed for HOULIHAN: Logesparan Priyaparan

Date: 2025-03-26

Signed for client by: Harvey scott

Date: 2025-05-20

The above inspections have been carried out and are acceptable/unacceptable

Non Conformities/Comments

Reason for non Conformities/Comments: na

Signed for HOULIHAN: Logesparan Priyaparan

Date: 2025-03-26

Signed for client by: Harvey scott

Date: 2025-05-20