

OUT OF TOLERANCE PILE REMEDIATION




Typical Section




Typical Plan

Detail A

Typical Ground Beam Remedial Detail - Pile displaced laterally



Typical Section



Typical Plan

Detail B

Typical Ground Beam Remedial Detail - Pile displaced longitudinally