

HEALTH, SAFETY & ENVIRONMENT

It is the responsibility of the client to ensure that those undertaking the works are competent and experienced in the type of work to be

In addition to the hazards usually associated with the types of work detailed on this drawing, the following specific hazards have been identified through design risk assessment. The planning and execution of the works should take into account all usual and specific

Hazards should also be taken into account in the maintenance,

Live services may be present on site

Existing ground is/may be contaminated

Deep excavations necessary

Ground conditions may be unstable during excavation

The stability of adjacent foundations will need to be considered during excavation works

All dimensions are in millimetres (mm) and levels in metres

- The copyright in this drawing belongs to Structa LLP; the designs and details may not be used on any project other than
- Where CAD or BIM files of the drawing are issued, they are provided for the convenience of others, and shall not be used for construction purposes or relied upon for accuracy or
- Topographical survey based on Hook Survey Partnership drawing number S21/8261/01. Layout based on Persimmon Homes drawing number 634-Con-100 Rev.

C9 18.08.25 NEW LAYOUT ADDED, GARDEN STEP ADDED C8 16.06.25 PLOT 3-9 BOUNDARY MOVED. POND AMENDED. PATHS AND EV BRUSH STRIP ADDED GARAGE C7 13.03.25 RETAINING WALLS REMOVED TO REAR OF PLOTS C6 | 17.02.25 | 14-16 AND 7-8. GRAVEL BOARD UPDATED IN | GE | TL C5 | 12.02.25 | LAYOUT UPDATED. PLOTS 8 AND 9 MOVED. SCREEN C4 | 14.01.25 | POS LEVELS UPDATED. BLOCK PAVING COLOURS C3 18.12.24 BOUNDARY TREATMENTS, RETAINING AND GATE C2 07.11.24 PLOT 3 ADDED AND CAR BARN AMENDED. P15-16 BOUNDARY AMENDED. CONSTRUCTION ISSUE Description Drawn Checked Approved

FOR CONSTRUCTION

LAND AT BASSETTS FARM, HORSMONDEN, KENT - PHASE 1

EXTERNAL WORKS



Revision: **C9**