

Pre-Inspection Checklist Sub Structure Block Work to FFL	
<b>Project:</b> Brooklands college, Weybridge	<b>Date:</b> 06 December 2024
<b>Area:</b> Phase 1b	<b>Am / Pm:</b> AM
<b>Locaton:</b> Plot 184	<b>Drawing Number:</b> SA00394-0001-A-HT1-SUB
<b>Weather Condition:</b> Dry	<b>Sheet Number:</b> I

Table of Contents

- Setting Out Line & Level to Current Drawings
- Product Material Compliant With Engineers/Architect Specification
- Specified Bedding Depth, Colour & Mlxing Ratio to Specification
- Specified DPC Installed & at Correct Level
- Specified Wall Ties & Air Vents Installed at Correct Location & Height
- DPC / Membrane Installed as Per Specification
- Brick Type
- Lintel Bearing

**Completed By:** James Brydon  
**Date Completed:** 06 December 2024

**Completed By:** James Brydon  
**Date Completed:** 06 December 2024

Specified Bedding Depth, Colour & Mixing Ratio to Specification

**Completed By:** James Brydon  
**Date Completed:** 06 December 2024

Specified DPC Installed & at Correct Level

**Completed By:** James Brydon

**Date Completed:** 06 December 2024

Specified Wall Ties & Air Vents Installed at Correct Location & Height

**Completed By:** James Brydon  
**Date Completed:** 06 December 2024

**Completed By:** James Brydon  
**Date Completed:** 06 December 2024

**Completed By:** James Brydon

**Date Completed:** 06 December 2024

CALA				Brookland						
				External Materials Schedule						
Plot Number	Plot Name	Dwelling Type	Ordering Item Reference	Masonry Finish	Tile/Hanging/Cladding Colour	Brick Type	Brick Colour	Window Type	Window Colour	Cladding
10	101	House	W10a (June 16)	Painting brickwork	N/A	Shank Facing Brick Type 2 - MODKERSHOP PCC finished face	Type 2 - First Quality Brick	UPVC cladding	RAL 7021	N/A
10	102	House	W10b (June 16)	Painting brickwork & Pave Floor Cement Tiles effect central heating	Flake cement under effect central heating - Limes/Travertine Pave "Mangrove Bay" or similar	Shank Facing Brick Type 2 - MODKERSHOP PCC finished face	Type 2 - First Quality Brick	UPVC cladding	RAL 7021	N/A
10	103	House	W10c (June 16)	Painting brickwork	N/A	Shank Facing Brick Type 2 - MODKERSHOP PCC finished face	Type 2 - First Quality Brick	UPVC cladding	RAL 7021	N/A
10	104	House	W10d	Flake Cement Tiles effect central heating & Pave Floor Cement Tiles effect central heating	Flake cement under effect central heating - Limes/Travertine Pave "Mangrove Bay" or similar	Shank Facing Brick Type 2 - MODKERSHOP PCC finished face	Type 2 - First Quality Brick	UPVC cladding	RAL 7021	N/A
10	105	House	W10e	Painting brickwork & Pave Floor Cement Tiles effect central heating	Flake cement under effect central heating - Limes/Travertine Pave "Mangrove Bay" or similar	Shank Facing Brick Type 2 - MODKERSHOP PCC finished face	Type 2 - First Quality Brick	UPVC cladding	RAL 7021	N/A
10	106	House	W10f	Flake Cement Tiles effect central heating & Pave Floor Cement Tiles effect central heating	Flake cement under effect central heating - Limes/Travertine Pave "Mangrove Bay" or similar	Shank Facing Brick Type 2 - MODKERSHOP PCC finished face	Type 2 - First Quality Brick	UPVC cladding	RAL 7021	N/A
10	107	House	W10g	Painting brickwork & Flare Floor Cement Tiles effect central heating	Flake cement under effect central heating - Limes/Travertine Pave "Mangrove Bay" or similar	Shank Facing Brick Type 2 - MODKERSHOP PCC finished face	Type 2 - First Quality Brick	UPVC cladding	RAL 7021	N/A
10	108	House	W10h	Painting brickwork & Flare Floor Cement Tiles effect central heating	Flake cement under effect central heating - Limes/Travertine Pave "Mangrove Bay" or similar	Shank Facing Brick Type 2 - MODKERSHOP PCC finished face	Type 2 - First Quality Brick	UPVC cladding	RAL 7021	N/A
10	109	House	W10i	Painting brickwork & Pave Floor Cement Tiles effect central heating	Flake cement under effect central heating - Limes/Travertine Pave "Mangrove Bay" or similar	Shank Facing Brick Type 2 - MODKERSHOP PCC finished face	Type 2 - First Quality Brick	UPVC cladding	RAL 7021	N/A
10	110	House	W10j	Painting brickwork & Pave Floor Cement Tiles effect central heating	Flake cement under effect central heating - Limes/Travertine Pave "Mangrove Bay" or similar	Shank Facing Brick Type 2 - MODKERSHOP PCC finished face	Type 2 - First Quality Brick	UPVC cladding	RAL 7021	N/A
10	111	House	W10k (June 16)	Painting brickwork	N/A	Shank Facing Brick Type 2 - MODKERSHOP PCC finished face	Type 2 - First Quality Brick	UPVC cladding	RAL 7021	N/A
10	112	House	W10l (June 16)	Flake Cement Tiles effect central heating & Pave Floor Cement Tiles effect central heating	Flake cement under effect central heating - Limes/Travertine Pave "Mangrove Bay" or similar	Shank Facing Brick Type 2 - MODKERSHOP PCC finished face	Type 2 - First Quality Brick	UPVC cladding	RAL 7021	N/A



Completed By: James Brydon

Date Completed: 06 December 2024



Proceed/not proceed

Reason for Rejection/Comments: Proceed

Signed for HOULIHAN: James Brydon

Date: 2024-12-06

Signed for client by:

Date:

The above inspections have been carried out and are acceptable/unacceptable

Non Conformities/Comments

Reason for non Conformities/Comments: na

Signed for HOULIHAN: James Brydon

Date: 2024-12-06

Signed for client by:

Date: