



There are no assets within this map area



There are no assets within this map area



There are no assets within



There are no assets within this map area



There are no assets within this map area



There are no assets wi this map area



There are no assets within this map area



There are no assets within this map area



There are no assets within



There are no assets within this map area



There are no assets within this map area



There are no assets wi this map area



There are no assets within this map area



There are no assets within this map area



There are no assets within this map area



There are no assets within this map area

Tank



There are no assets within this map area



There are no assets withis map area



There are no assets within this map area



There are no assets within this map area

The Mill House

digdat

There are no assets within this map area

digdat

Okthonice Survey & Grown Copyright, 100018507

There are no assets within

this map area

Mill Pond Nursery



There are no assets within this map area



There are no assets w this map area





Mill Pond Farm

diadat

Hilltop Yard

diadat

debbie.wilson@survatec.com

diada

(c) Crown copyright and database rights 2022 Ordnance Survey 100019209

Date: 21/07/22

Scale: 1:1250

Map Centre: 554515,227636

Data updated: 30/05/22

Our Ref: 906523 - 4


Telecoms Plan A3

Important Information - please read The purpose of this plan is to identify Virgin Media apparatus. We have tried to make it as accurate as possible but we cannot warrant its accuracy. In addition, we caution that within Virgin Media apparatus there may be instances where mains voltage power cables have been placed inside green, rather than black ducting. Further details can be found using the "Affected Postcodes.pdf", which can be downloaded from this website. Therefore, you must not rely solely on this plan if you are carrying out any excavation or other works in the vicinity of Virgin Media apparatus. The actual position of any underground service must be verified by cable detection equipment, etc. and established on site before any mechanical plant is used. Accordingly, unless it is due to the negligence of Virgin Media, its employees or agents, Virgin Media will not have any liability for any omissions or inaccuracies in the plan or for any loss or damage caused or arising from the use of and/or any reliance on this plan. This plan is produced by Virgin Media Limited (c) Crown copyright and database rights 2022 Ordnance Survey 100019209.

Duct, Trench

Chamber / Pole

Cabinet







There are no assets within this map area



There are no assets within this map area



There are no assets within this map area



There are no assets within this map area



There are no assets within this map area



There are no assets w this map area



There are no assets within this map area



There are no assets within this map area



There are no assets within this map area



There are no assets within this map area



There are no assets within this map area



There are no assets wi this map area



There are no assets within this map area



There are no assets within this map area



There are no assets within this map area



There are no assets within this map area



There are no assets within this map area



There are no assets wi this map area



There are no assets within this map area



There are no assets within this map area



There are no assets within this map area



There are no assets within this map area



There are no assets within this map area



There are no assets w





diadat

diadat



debbie.wilson@survatec.com



(c) Crown copyright and database rights 2022 Ordnance Survey 100019209

Date: 21/07/22

Scale: 1:1250

Map Centre: 554531,227362

Data updated: 30/05/22

Our Ref: 906523 - 6

Telecoms Plan A3

Important Information - please read The purpose of this plan is to identify Virgin Media apparatus. We have tried to make it as accurate as possible but we cannot warrant its accuracy. In addition, we caution that within Virgin Media apparatus there may be instances where mains voltage power cables have been placed inside green, rather than black ducting. Further details can be found using the "Affected Postcodes.pdf", which can be downloaded from this website. Therefore, you must not rely solely on this plan if you are carrying out any excavation or other works in the vicinity of Virgin Media apparatus. The actual position of any underground service must be verified by cable detection equipment, etc. and established on site before any mechanical plant is used. Accordingly, unless it is due to the negligence of Virgin Media, its employees or agents, Virgin Media will not have any liability for any omissions or inaccuracies in the plan or for any loss or damage caused or arising from the use of and/or any reliance on this plan. This plan is produced by Virgin Media Limited (c) Crown copyright and database rights 2022 Ordnance Survey 100019209.

Duct, Trench

Chamber / Pole

•

Cabinet 3



