

Pre-Inspection Checklist	
Project: Taylor Wimpey North Finchley Site	Date: 08 April 2025
Area: Block T4	Am / Pm: AM
Locaton: Block T4	Drawing Number: 10559-250 C9
Weather Condition: Dry / Mild	Sheet Number: 22227-BM-T4 T5-L1-DR-A-151 C1

Table of Contents

- Setting Out / Cross Check With Arch Plans
- Bedding
- Pipes
- Testing Priot to Covering (air or water)
- Backfilling / Casting In
- Incoming Services
- Additonal Measures Taken

Completed By: LP
Date Completed: 08 April 2025



Completed By: LP

Date Completed: 08 April 2025



Completed By: LP

Date Completed: 08 April 2025

material -> Upvc
line -> Yes
level / fill -> Yes
support / restraint -> Yes
rocker lengths -> Yes
lintel clearance -> Yes



Testing Priot to Covering (air or water)

Completed By: LP
Date Completed: 08 April 2025

Completed By: LP

Date Completed: 08 April 2025

Material Used -> As dug / Shingle

Plant Used -> N/A



Completed By: LP

Date Completed: 08 April 2025

Cross Check With Arch for Setting Out -> Yes

Correct ducting used -> Yes

EVCP's -> NA

Incoming water services to follow guildlines as per NHBC -> Yes



Completed By: LP

Date Completed: 08 April 2025

Additional Measures:

All Pipes & Penetrstions to be Sealed -> Yes



Proceed/not proceed

Reason for Rejection/Comments: All the internal drainage has been inspected by NHBC

Signed for HOULIHAN: Logesparan Priyaparan

Date: 2025-04-08

Signed for client by: Harvey scott

Date: 2025-05-20

The above inspections have been carried out and are acceptable/unacceptable

Non Conformities/Comments

Reason for non Conformities/Comments: na

Signed for HOULIHAN: Logesparan Priyaparan

Date: 2025-04-08

Signed for client by: Harvey scott

Date: 2025-05-20