



Pre-Inspection Checklist External Drainage	
<b>Project:</b> Taylor Wimpey North Finchley Site	<b>Date:</b> 10 March 2025
<b>Area:</b> Block T5	<b>Am / Pm:</b> AM
<b>Locaton:</b> Block T5	<b>Drawing Number:</b> 10559-250 C8
<b>Weather Condition:</b> Fine / mild	<b>Sheet Number:</b> 1

Table of Contents

- Setting Out / Installation as per Design Drawings
- Bedding
- Pipes
- Testing Priot to Covering
- Backfilling
- Additonal Measures Taken

**Completed By:** LP

**Date Completed:** 10 March 2025



Bedding

**Completed By:** LP  
**Date Completed:** 10 March 2025

**Completed By:** LP

**Date Completed:** 10 March 2025

- (a) material Upvc
- (b) material Yes
- (c) material Yes
- (d) material Yes



Testing Priot to Covering

**Completed By:** LP

**Date Completed:** 10 March 2025



## Backfilling

**Completed By:** LP

**Date Completed:** 10 March 2025





## Additional Measures Taken

**Completed By:** LP

**Date Completed:** 10 March 2025



Proceed/not proceed

Reason for Rejection/Comments: na

Signed for HOULIHAN: Logesparan Priyaparan

Date: 2025-03-10

Signed for client by: Harvey scott

Date: 2025-05-20

The above inspections have been carried out and are acceptable/unacceptable

Non Conformities/Comments

Reason for non Conformities/Comments: na

Signed for HOULIHAN: Logesparan Priyaparan

Date: 2025-03-10

Signed for client by: Harvey scott

Date: 2025-05-20