

Pre-Inspection Checklist	
Project: Taylor Wimpey North Finchley Site	Date: 10 March 2025
Area: Block T5	Am / Pm: AM
Locaton: Block T5	Drawing Number: 10559-250 C8
Weather Condition: Fine / mild	Sheet Number: 22227-BM3-T4T5-L0-DR-A-150 C2

Table of Contents

- Setting Out / Cross Check With Arch Plans
- Bedding
- Pipes
- Testing Priot to Covering (air or water)
- Backfilling / Casting In
- Incoming Services
- Additonal Measures Taken

Completed By: LP

Date Completed: 10 March 2025



Bedding

Completed By: LP

Date Completed: 10 March 2025



Completed By: LP

Date Completed: 10 March 2025

- material -> Upvc
- line -> Yes
- level / fill -> Yes
- support / restraint -> Yes
- rocker lenghts -> Yes
- intel clearance -> Yes



Testing Priot to Covering (air or water)

Completed By: LP
Date Completed: 10 March 2025

Completed By: LP

Date Completed: 10 March 2025

Material Used -> 10mm Shingle / as dug

Plant Used -> No



Completed By: LP

Date Completed: 10 March 2025

Cross Check With Arch for Setting Out -> Yes

Correct ducting used -> Yes

EVCP's -> N/A

Incoming water services to follow guildlines as per NHBC -> Yes



Completed By: LP

Date Completed: 10 March 2025

Additional Measures:
All Pipes & Penetrstions to be Sealed -> Yes



Proceed/not proceed

Reason for Rejection/Comments: All the internal drainage has been inspected by NHBC

Signed for HOULIHAN: Logesparan Priyaparan

Date: 2025-03-10

Signed for client by: Harvey scott

Date: 2025-05-08

The above inspections have been carried out and are acceptable/unacceptable

Non Conformities/Comments

Reason for non Conformities/Comments: na

Signed for HOULIHAN: Logesparan Priyaparan

Date: 2025-03-10

Signed for client by: Harvey scott

Date: 2025-05-08