



Pre-Inspection Checklist Sub Structure Block Work to FFL	
Project: Taylor Wimpey North Finchley Site	Date: 25 February 2025
Area: Block T5	Am / Pm: PM
Locaton: Block T5	Drawing Number: 22227-BM3-T4T5-L0-DR-A-150 C2
Weather Condition: Fine / mild	Sheet Number: 1

Table of Contents

- Setting Out Line & Level to Current Drawings
- Product Material Compliant With Engineers/Architect Specification
- Specified Bedding Depth, Colour & Mlxing Ratio to Specification
- Specified DPC Installed & at Correct Level
- Specified Wall Ties & Air Vents Installed at Correct Location & Height
- DPC / Membrane Installed as Per Specification
- Brick Type
- Lintel Bearing

Completed By: LP

Date Completed: 25 February 2025



Completed By: LP

Date Completed: 25 February 2025



Completed By: LP

Date Completed: 25 February 2025



Completed By: LP

Date Completed: 25 February 2025



Completed By: LP

Date Completed: 25 February 2025



Completed By: LP

Date Completed: 25 February 2025



Completed By: LP

Date Completed: 25 February 2025



Completed By: LP

Date Completed: 25 February 2025



Proceed/not proceed

Reason for Rejection/Comments: All the sub structure block work has been inspected by NHBC

Signed for HOULIHAN: Logesparan Priyaparan

Date: 2025-02-25

Signed for client by: Harvey scott

Date: 2025-05-08

The above inspections have been carried out and are acceptable/unacceptable

Non Conformities/Comments

Reason for non Conformities/Comments: na

Signed for HOULIHAN: Logesparan Priyaparan

Date: 2025-02-25

Signed for client by: Harvey scott

Date: 2025-05-08