

Pre-Inspection Checklist	
Project: Taylor Wimpey North Finchley site	Date: 10 December 2024
Area: Block D internal drainage and services	Am / Pm: PM
Locaton: Block D	Drawing Number: 10559-250 C8
Weather Condition: Dry / Cold	Sheet Number: 22227-BM-D-L1-DR-A-150 C3

Table of Contents

- Setting Out / Cross Check With Arch Plans
- Bedding
- Pipes
- Testing Priot to Covering (air or water)
- Backfilling / Casting In
- Incoming Services
- Additonal Measures Taken

Completed By: LP

Date Completed: 10 December 2024



Completed By: LP
Date Completed: 10 December 2024



Completed By: LP

Date Completed: 10 December 2024

material -> Upvc
line -> Yes
level / fill -> Yes
support / restraint -> Yes
rocker lenghts -> Yes
intel clearance -> Yes



Completed By: LP
Date Completed: 28 March 2025

Completed By: LP

Date Completed: 10 December 2024

Material Used -> 10mm shingle

Plant Used -> NA



Completed By: LP

Date Completed: 10 December 2024

Cross Check With Arch for Setting Out -> LP

Correct ducting used -> LP

EVCP's -> N/A

Incoming water services to follow guildlines as per NHBC -> LP



Additional Measures Taken

Completed By: LP

Date Completed: 10 December 2024

Additional Measures:



Proceed/not proceed
Reason for Rejection/Comments: na
Signed for HOULIHAN: Logesparan Priyaparan Date: 2024-12-10 Signed for client by: Harvey scott Date: 2025-03-28 The above inspections have been carried out and are acceptable/unacceptable

Non Conformities/Comments
Reason for non Conformities/Comments: na
Signed for HOULIHAN: Logesparan Priyaparan Date: 2024-12-10 Signed for client by: Harvey scott Date: 2025-03-28