



Pre-Inspection Checklist Sub Structure Block Work to FFL	
Project: Taylor Wimpey North Finchley site	Date: 11 November 2024
Area: Block D	Am / Pm: PM
Locaton: Block D	Drawing Number: 22227-BM-D-L1-DR-A-150 C4
Weather Condition: Dry and mild	Sheet Number: 22227-BM-D-L1-DR-A-151 C7

Table of Contents

- Setting Out Line & Level to Current Drawings
- Product Material Compliant With Engineers/Architect Specification
- Specified Bedding Depth, Colour & Mlxing Ratio to Specification
- Specified DPC Installed & at Correct Level
- Specified Wall Ties & Air Vents Installed at Correct Location & Height
- DPC / Membrane Installed as Per Specification
- Brick Type
- Lintel Bearing

Completed By: LP

Date Completed: 11 November 2024



Completed By: LP

Date Completed: 11 November 2024



Completed By: LP

Date Completed: 11 November 2024



Specified DPC Installed & at Correct Level

Completed By: LP

Date Completed: 11 November 2024

Completed By: LP

Date Completed: 11 November 2024



Completed By: LP

Date Completed: 11 November 2024



Completed By: LP

Date Completed: 11 November 2024



Completed By: LP

Date Completed: 11 November 2024



Proceed/not proceed
Reason for Rejection/Comments: na
Signed for HOULIHAN: Logesparan Priyaparan Date: 2024-11-11 Signed for client by: Harvey scott Date: 2025-03-28 The above inspections have been carried out and are acceptable/unacceptable

Non Conformities/Comments
Reason for non Conformities/Comments: na
Signed for HOULIHAN: Logesparan Priyaparan Date: 2025-03-04 Signed for client by: Harvey scott Date: 2025-03-28