

Pre-Inspection Checklist	
Project: Taylor Wimpey North Finchley Site	Date: 11 July 2025
Area: Internal Drainage and services	Am / Pm: AM
Locaton: Block T1 - Plot 1 - 7	Drawing Number: 10559-250 C11
Weather Condition: Fine / mild	Sheet Number: 22227-BM-T1-L1-DR-A-151 C3

Table of Contents

- Setting Out / Cross Check With Arch Plans
- Bedding
- Pipes
- Testing Priot to Covering (air or water)
- Backfilling / Casting In
- Incoming Services
- Additonal Measures Taken

Completed By: LP

Date Completed: 11 July 2025



Bedding

Completed By: LP

Date Completed: 11 July 2025



Completed By: LP

Date Completed: 11 July 2025

material -> UPVC

line -> Yes

level / fill -> Yes

support / restraint -> Yes

rocker lengths -> Yes

lintel clearance -> Yes



Testing Priot to Covering (air or water)

Completed By: LP
Date Completed: 11 July 2025

Completed By: LP

Date Completed: 11 July 2025

Material Used -> As dug / Shingle

Plant Used -> 360 Excavators



Completed By: LP

Date Completed: 11 July 2025

Cross Check With Arch for Setting Out -> Yes

Correct ducting used -> Yes

EVCP's -> NA

Incoming water services to follow guidelines as per NHBC -> Yes



Completed By: LP

Date Completed: 11 July 2025

Additional Measures:

All Pipes & Penetrations to be Sealed -> Yes



Proceed/not proceed

Reason for Rejection/Comments: Internal drainage and services has been inspected by NHBC inspector and Taylor Wimpey Site manager

Signed for HOULIHAN: Logesparan Priyaparan

Date: 2025-07-11

Signed for client by: Harvey scott

Date: 2025-07-11

The above inspections have been carried out and are acceptable/unacceptable

Non Conformities/Comments

Reason for non Conformities/Comments: All good and proceed jet floor installation

Signed for HOULIHAN: Logesparan Priyaparan

Date: 2025-07-11

Signed for client by: Harvey scott

Date: 2025-07-11