



Pre-Inspection Checklist Sub Structure Block Work to FFL	
Project: Taylor Wimpey North Finchley Site	Date: 13 June 2025
Area: Sub structure Block work	Am / Pm: AM
Locaton: Block T1 - Plot 1-7	Drawing Number: 22227-BM3-T1-L0-DR-A-150 C4
Weather Condition: Fine / mild	Sheet Number: 22227-BM-T1-L1-DR-A-151 C3

Table of Contents

- Setting Out Line & Level to Current Drawings
- Product Material Compliant With Engineers/Architect Specification
- Specified Bedding Depth, Colour & Mlxing Ratio to Specification
- Specified DPC Installed & at Correct Level
- Specified Wall Ties & Air Vents Installed at Correct Location & Height
- DPC / Membrane Installed as Per Specification
- Brick Type
- Lintel Bearing

Completed By: LP
Date Completed: 11 July 2025



Completed By: LP

Date Completed: 11 July 2025



Completed By: LP

Date Completed: 11 July 2025



Specified DPC Installed & at Correct Level

Completed By: LP

Date Completed: 11 July 2025

Completed By: LP

Date Completed: 11 July 2025



Completed By: LP

Date Completed: 11 July 2025



Completed By: LP

Date Completed: 11 July 2025



Completed By: LP

Date Completed: 11 July 2025



Proceed/not proceed

Reason for Rejection/Comments: Substructure block work has been inspected by NHBC inspector and Taylor Wimpey Site manager

Signed for HOULIHAN: Logesparan Priyaparan

Date: 2025-07-11

Signed for client by: Harvey scott

Date: 2025-07-11

The above inspections have been carried out and are acceptable/unacceptable

Non Conformities/Comments

Reason for non Conformities/Comments: All good and proceed jet floor installation

Signed for HOULIHAN: Logesparan Priyaparan

Date: 2025-07-11

Signed for client by: Harvey scott

Date: 2025-07-11