

Pre-Inspection Checklist	
Project: Taylor Wimpey North Finchley Site	Date: 24 July 2025
Area: Block and beam floor	Am / Pm: AM
Locaton: Block T1	Drawing Number: 2407001 Block T1 - Bison precast
Weather Condition: Fine / mild	Sheet Number: 22227-BM-T1-L1-DR-A-151 C3

Table of Contents



- Setting Out Line & Level to Current Drawings
- Product Material Compliant to Engineer Architects Specification
- Rebar / Mesh if to Specified Drawing
- Correct Depth of Concrete Achieved
- Concrete Specification for Tolerance Achieved
- Additonal Measures Taken

Completed By: LP
Date Completed: 24 July 2025



Completed By: LP

Date Completed: 24 July 2025



Completed By: LP

Date Completed: 24 July 2025

(a) material POLYPIPE

Completed By: LP
Date Completed: 24 July 2025



Completed By: LP

Date Completed: 24 July 2025



Additional Measures Taken

Completed By: LP

Date Completed: 24 July 2025

Proceed/not proceed

Reason for Rejection/Comments: Jet floor beam and EPS infill has been inspected by TW site managers DPM and joints, waterproof membrane and DPC has been inspected by TW site managers

Signed for HOULIHAN: Logesparan Priyaparan

Date: 2025-07-24

Signed for client by: Harvey scott

Date: 2025-07-24

The above inspections have been carried out and are acceptable/unacceptable

Non Conformities/Comments

Reason for non Conformities/Comments: na

Signed for HOULIHAN: Logesparan Priyaparan

Date: 2025-07-24

Signed for client by: Harvey scott

Date: 2025-07-24