

Pre-Inspection Checklist	
Project: Taylor Wimpey North Finchley Site	Date: 25 February 2025
Area: Block BC	Am / Pm: AM
Locaton: BLOCK BC	Drawing Number: 10559-250 C8
Weather Condition: Fine / mild	Sheet Number: 22227-BM-BC-L1-DR-A-150 C6

Table of Contents

- Setting Out / Cross Check With Arch Plans
- Bedding
- Pipes
- Testing Priot to Covering (air or water)
- Backfilling / Casting In
- Incoming Services
- Additonal Measures Taken

Completed By: LP

Date Completed: 25 February 2025



Completed By: LP

Date Completed: 25 February 2025



Completed By: LP

Date Completed: 25 February 2025

material -> UPVC
line -> Yes
level / fill -> Yes
support / restraint -> Yes
rocker lenghts -> Yes
lintel clearance -> Yes



Completed By: LP
Date Completed: 25 February 2025

Completed By: LP

Date Completed: 25 February 2025

Material Used -> As dug / Shingle

Plant Used -> 360 Excavators



Completed By: LP

Date Completed: 25 February 2025

Cross Check With Arch for Setting Out -> Yes

Correct ducting used -> Yes

EVCP's -> Yes

Incoming water services to follow guildlines as per NHBC -> Yes



Additional Measures Taken

Completed By: LP

Date Completed: 25 February 2025

Additional Measures:

All Pipes & Penetrations to be Sealed -> Yes



Proceed/not proceed

Reason for Rejection/Comments: All the internal drainage has been inspected by NHBC

Signed for HOULIHAN: Logesparan Priyaparan

Date: 2025-02-25

Signed for client by: Harvey scott

Date: 2025-03-28

The above inspections have been carried out and are acceptable/unacceptable

Non Conformities/Comments

Reason for non Conformities/Comments: All the internal drainage has been inspected by NHBC inspector

Signed for HOULIHAN: Logesparan Priyaparan

Date: 2025-02-25

Signed for client by: Harvey scott

Date: 2025-03-28