



Pre pour inspection 12 & Daily record photos	
Project: Gas Road	Date: 01 May 2025
Area: Pre pour inspection 12 & Daily record photos	Am / Pm: AM
Locaton:	Drawing Number:
Weather Condition:	Sheet Number:

Table of Contents

- Formation Level - checked to provide +5mm-15mm
- Rebar - placed at correct level & sufficiently lapped
- Shutters = secure & in line
- K-Form - in correct position
- Membrane - clean & in position
- Volume - of concrete poured
- Cubes - taken

Formation Level - checked to provide +5mm-15mm

Completed By: PK
Date Completed: 01 May 2025
Comment: na

Rebar - placed at correct level & sufficiently lapped

Completed By: PK
Date Completed: 01 May 2025
Comment: na

Shutters = secure & in line

Completed By: PK
Date Completed: 01 May 2025
Comment: na

K-Form - in correct position

Completed By: PK

Date Completed: 01 May 2025

Comment: na

Membrane - clean & in position

Completed By: PK

Date Completed: 01 May 2025



Comment: nabr>

Volume - of concrete poured

Completed By: PK
Date Completed: 01 May 2025
Comment: 147 Meters

Completed By: PK
Date Completed: 01 May 2025
Comment: Bretts





Proceed/not proceed

Reason for Rejection/Comments: na

Signed for HOULIHAN:

Date:

Signed for client by:

Date:

The above inspections have been carried out and are acceptable/unacceptable

Non Conformities/Comments

Reason for non Conformities/Comments: na

Signed for HOULIHAN:

Date:

Signed for client by:

Date: