



| Pre pour inspection 18 & Daily record photos | |
|---|--------------------------|
| Project: Gas Road | Date: 13 May 2025 |
| Area: Pre pour inspection 18 & Daily record photos | Am / Pm: AM |
| Locaton: | Drawing Number: |
| Weather Condition: | Sheet Number: |

Table of Contents

- Formation Level - checked to provide +5mm-15mm
- Rebar - placed at correct level & sufficiently lapped
- Shutters = secure & in line
- K-Form - in correct position
- Membrane - clean & in position
- Volume - of concrete poured
- Cubes - taken

Formation Level - checked to provide +5mm-15mm

Completed By: Pat Kearney

Date Completed: 13 May 2025

Comment: na

Rebar - placed at correct level & sufficiently lapped

Completed By: Pat Kearney

Date Completed: 13 May 2025

Comment: na

Shutters = secure & in line

Completed By: Pat Kearney

Date Completed: 13 May 2025

Comment: na

K-Form - in correct position

Completed By: Pat Kearney

Date Completed: 13 May 2025

Comment: na

Membrane - clean & in position

Completed By: Pat Kearney


Date Completed: 13 May 2025

Comment: nabr>

Volume - of concrete poured

Completed By: Pk
Date Completed: 13 May 2025
Comment: na

Completed By: Pk
Date Completed: 13 May 2025
Comment: na





Proceed/not proceed

Reason for Rejection/Comments: na

Signed for HOULIHAN:

Date:

Signed for client by:

Date:

The above inspections have been carried out and are acceptable/unacceptable

Non Conformities/Comments

Reason for non Conformities/Comments: na

Signed for HOULIHAN:

Date:

Signed for client by:

Date: