



Pre-Inspection Checklist Sub Structure Block Work to FFL	
Project: Henham	Date: 23 April 2025
Area: Site	Am / Pm: AM
Locaton: Plot 18 to 19	Drawing Number: N/A
Weather Condition: Dry	Sheet Number: N/A

Table of Contents

- Setting Out Line & Level to Current Drawings
- Product Material Compliant With Engineers/Architect Specification
- Specified Bedding Depth, Colour & Mlxing Ratio to Specification
- Specified DPC Installed & at Correct Level
- Specified Wall Ties & Air Vents Installed at Correct Location & Height
- DPC / Membrane Installed as Per Specification
- Brick Type
- Lintel Bearing

Completed By: Lf

Date Completed: 23 April 2025



Completed By: RG
Date Completed: 24 April 2025

Specified Bedding Depth, Colour & Mixing Ratio to Specification

Completed By: RG
Date Completed: 24 April 2025

Specified DPC Installed & at Correct Level

Completed By: RG

Date Completed: 24 April 2025

Completed By: RG

Date Completed: 24 April 2025



Completed By: RG
Date Completed: 02 June 2025

Completed By: Rg

Date Completed: 02 June 2025



Completed By: RG

Date Completed: 24 April 2025



Proceed/not proceed

Reason for Rejection/Comments: na

Signed for HOULIHAN: RG

Date: 2025-04-24

Signed for client by:

Date:

The above inspections have been carried out and are acceptable/unacceptable

Non Conformities/Comments

Reason for non Conformities/Comments: na

Signed for HOULIHAN: RG

Date: 2025-04-24

Signed for client by:

Date: