



Pre-Inspection Checklist Sub Structure Block Work to FFL	
Project: Henham	Date: 01 May 2025
Area: Site	Am / Pm: PM
Locaton: Plot 20/21	Drawing Number: C86840-jnp-10-00-dr-s-2502
Weather Condition: Dry	Sheet Number: N/A

Table of Contents

- Setting Out Line & Level to Current Drawings
- Product Material Compliant With Engineers/Architect Specification
- Specified Bedding Depth, Colour & Mlxing Ratio to Specification
- Specified DPC Installed & at Correct Level
- Specified Wall Ties & Air Vents Installed at Correct Location & Height
- DPC / Membrane Installed as Per Specification
- Brick Type
- Lintel Bearing

Completed By: RG

Date Completed: 01 May 2025



Completed By: RG
Date Completed: 01 May 2025

Specified Bedding Depth, Colour & Mixing Ratio to Specification

Completed By: RG
Date Completed: 01 May 2025

Completed By: RG

Date Completed: 01 May 2025



Completed By: RG

Date Completed: 01 May 2025



Completed By: RG
Date Completed: 01 May 2025

Completed By: RG

Date Completed: 01 May 2025



Completed By: RG

Date Completed: 01 May 2025



Proceed/not proceed

Reason for Rejection/Comments: na

Signed for HOULIHAN: RG

Date: 2025-05-01

Signed for client by:

Date:

The above inspections have been carried out and are acceptable/unacceptable

Non Conformities/Comments

Reason for non Conformities/Comments: na

Signed for HOULIHAN: RG

Date: 2025-05-01

Signed for client by:

Date: