



Pre-Inspection Checklist Sub Structure Block Work to FFL	
Project: Henham	Date: 04 August 2025
Area: Site	Am / Pm: PM
Locaton: Plot 41	Drawing Number: 24403-ash-200
Weather Condition: Mixed	Sheet Number: N/A

Table of Contents

- Setting Out Line & Level to Current Drawings
- Product Material Compliant With Engineers/Architect Specification
- Specified Bedding Depth, Colour & Mlxing Ratio to Specification
- Specified DPC Installed & at Correct Level
- Specified Wall Ties & Air Vents Installed at Correct Location & Height
- DPC / Membrane Installed as Per Specification
- Brick Type
- Lintel Bearing

Completed By: RG

Date Completed: 04 August 2025



Completed By: RG

Date Completed: 04 August 2025



Completed By: RG

Date Completed: 04 August 2025



Specified DPC Installed & at Correct Level

Completed By: RG

Date Completed: 04 August 2025

Completed By: RG

Date Completed: 04 August 2025



Completed By: RG
Date Completed: 04 August 2025

Completed By: Rg

Date Completed: 04 August 2025



Completed By: RG

Date Completed: 04 August 2025



Proceed/not proceed

Reason for Rejection/Comments: na

Signed for HOULIHAN: RG

Date: 2025-08-04

Signed for client by:

Date:

The above inspections have been carried out and are acceptable/unacceptable

Non Conformities/Comments

Reason for non Conformities/Comments: na

Signed for HOULIHAN: RG

Date: 2025-08-04

Signed for client by:

Date: