

Pre-Inspection Checklist	
Project: Basildon	Date: 24 July 2025
Area: 4b	Am / Pm: AM
Locaton: 681-682	Drawing Number: R681 c2
Weather Condition: Dry	Sheet Number: 1

Table of Contents

- Setting Out Line & Level to Current Drawings
- Correct Formation Depth Achieved
- Concrete Blinding to Depth Specified
- Rebar to Specified Drawing
- Concrete Specification
- Concrete Specification for Finish
- Post Pour Level Check

Completed By: Aaron
Date Completed: 03 July 2025

Completed By: Aaron

Date Completed: 03 July 2025



Concrete Blinding to Depth Specified

Completed By: Aaron
Date Completed: 03 July 2025
(a) material POLYPIPE

Rebar to Specified Drawing

Completed By: Aaron
Date Completed: 03 July 2025

Concrete Specification

Completed By: Aaron
Date Completed: 03 July 2025

Concrete Specification for Finish

Completed By: Aaron
Date Completed: 03 July 2025

Completed By: Aaron
Date Completed: 03 July 2025
Additional Measures:
Claymaster -> Yes
Cellcore -> Yes



Proceed/not proceed

Reason for Rejection/Comments: Proceed

Signed for HOULIHAN: Aaron

Date: 2025-07-03

Signed for client by:

Date:

The above inspections have been carried out and are acceptable/unacceptable

Non Conformities/Comments

Reason for non Conformities/Comments: na

Signed for HOULIHAN:

Date:

Signed for client by:

Date: