



Pre-Inspection Checklist Sub Structure Block Work to FFL	
<b>Project:</b> Basildon	<b>Date:</b> 24 July 2025
<b>Area:</b> Basildon 4b	<b>Am / Pm:</b> AM
<b>Locaton:</b> 681-682	<b>Drawing Number:</b> Letchbetts0drs01
<b>Weather Condition:</b> Dry	<b>Sheet Number:</b> 2

Table of Contents

- Setting Out Line & Level to Current Drawings
- Product Material Compliant With Engineers/Architect Specification
- Specified Bedding Depth, Colour & Mlxing Ratio to Specification
- Specified DPC Installed & at Correct Level
- Specified Wall Ties & Air Vents Installed at Correct Location & Height
- DPC / Membrane Installed as Per Specification
- Brick Type
- Lintel Bearing

Completed By: Aaron

Date Completed: 07 July 2025



**Completed By:** Aaron  
**Date Completed:** 07 July 2025

**Completed By:** Aaron

**Date Completed:** 07 July 2025



Specified DPC Installed & at Correct Level

**Completed By:** Aaron

**Date Completed:** 07 July 2025

Specified Wall Ties & Air Vents Installed at Correct Location & Height

**Completed By:** Aaron  
**Date Completed:** 07 July 2025

**Completed By:** Aaron  
**Date Completed:** 07 July 2025

Brick Type

**Completed By:** Aaron  
**Date Completed:** 07 July 2025



**Completed By:** Aaron  
**Date Completed:** 07 July 2025

Proceed/not proceed

Reason for Rejection/Comments: Proceed

Signed for HOULIHAN: Aaron

Date: 2025-07-07

Signed for client by:

Date:

The above inspections have been carried out and are acceptable/unacceptable

Non Conformities/Comments

Reason for non Conformities/Comments: na

Signed for HOULIHAN:

Date:

Signed for client by:

Date: