

Pre-Inspection Checklist	
Project: Basildon	Date: 19 August 2025
Area: 4b	Am / Pm: AM
Locaton: 677	Drawing Number:
Weather Condition: Dry	Sheet Number:

Table of Contents

- Setting Out Line & Level to Current Drawings
- Correct Formation Depth Achieved
- Concrete Blinding to Depth Specified
- Rebar to Specified Drawing
- Concrete Specification
- Concrete Specification for Finish
- Post Pour Level Check

Completed By: Aaron

Date Completed: 18 August 2025



Correct Formation Depth Achieved

Completed By: Aaron

Date Completed: 18 August 2025

Completed By: Aaron

Date Completed: 18 August 2025

(a) material POLYPIPE



Rebar to Specified Drawing

Completed By: Aaron

Date Completed: 18 August 2025

Concrete Specification

Completed By: Aaron

Date Completed: 18 August 2025

Concrete Specification for Finish

Completed By: Aaron

Date Completed: 18 August 2025

Post Pour Level Check

Completed By: Aaron
Date Completed: 18 August 2025
Additional Measures:
Claymaster -> Yes
Cellcore -> Yes

Proceed/not proceed

Reason for Rejection/Comments: na

Signed for HOULIHAN: Aaron

Date: 2025-08-18

Signed for client by:

Date:

The above inspections have been carried out and are acceptable/unacceptable

Non Conformities/Comments

Reason for non Conformities/Comments: na

Signed for HOULIHAN:

Date:

Signed for client by:

Date: