


Pre-Inspection Checklist Sub Structure Block Work to FFL	
Project: Brooklands college, Weybridge	Date: 11 December 2024
Area: Phase 1b	Am / Pm: AM
Locaton: Plot 175	Drawing Number: SA00394-0007-A-HT2-SUB
Weather Condition: Dry	Sheet Number: J

Table of Contents

- Setting Out Line & Level to Current Drawings
- Product Material Compliant With Engineers/Architect Specification
- Specified Bedding Depth, Colour & Mlxing Ratio to Specification
- Specified DPC Installed & at Correct Level
- Specified Wall Ties & Air Vents Installed at Correct Location & Height
- DPC / Membrane Installed as Per Specification
- Brick Type
- Lintel Bearing

Completed By: James Brydon

Date Completed: 11 December 2024



Completed By: James Brydon

Date Completed: 11 December 2024



Completed By: James Brydon

Date Completed: 11 December 2024



Specified DPC Installed & at Correct Level

Completed By: James Brydon

Date Completed: 11 December 2024

Completed By: James Brydon

Date Completed: 11 December 2024



Completed By: James Brydon
Date Completed: 11 December 2024

Completed By: James Brydon

Date Completed: 11 December 2024

[illegible]

Completed By: James Brydon

Date Completed: 11 December 2024



Proceed/not proceed

Reason for Rejection/Comments: FYI Darren Smoker. 3 courses trench block laid to achieve TOC level

Signed for HOULIHAN: James Brydon

Date: 2024-12-11

Signed for client by:

Date:

The above inspections have been carried out and are acceptable/unacceptable

Non Conformities/Comments

Reason for non Conformities/Comments: na

Signed for HOULIHAN: James Brydon

Date: 2024-12-11

Signed for client by:

Date: