




Pre-Inspection Checklist Sub Structure Block Work to FFL	
Project: Brooklands college, Weybridge	Date: 14 October 2025
Area: Phase 2B	Am / Pm: AM
Locaton: Plot 225	Drawing Number: SA00394-0102-A-HT9B-SUB
Weather Condition: Dry	Sheet Number: N/A

Table of Contents

- Setting Out Line & Level to Current Drawings
- Product Material Compliant With Engineers/Architect Specification
- Specified Bedding Depth, Colour & Mlxing Ratio to Specification
- Specified DPC Installed & at Correct Level
- Specified Wall Ties & Air Vents Installed at Correct Location & Height
- DPC / Membrane Installed as Per Specification
- Brick Type
- Lintel Bearing

Completed By: James Brydon

Date Completed: 14 October 2025



Specified Bedding Depth, Colour & Mixing Ratio to Specification

Completed By: James Brydon

Date Completed: 14 October 2025


Specified DPC Installed & at Correct Level

Completed By: James Brydon

Date Completed: 14 October 2025

Completed By: James Brydon

Date Completed: 14 October 2025




Completed By: James Brydon

Date Completed: 14 October 2025


Completed By: James Brydon

Date Completed: 14 October 2025

[illegible]

Completed By: James Brydon

Date Completed: 14 October 2025



Proceed/not proceed

Reason for Rejection/Comments: na

Signed for HOULIHAN: James Brydon

Date: 2025-10-14

Signed for client by:

Date:

The above inspections have been carried out and are acceptable/unacceptable

Non Conformities/Comments

Reason for non Conformities/Comments: na

Signed for HOULIHAN: James Brydon

Date: 2025-10-14

Signed for client by:

Date: