


| Pre-Inspection Checklist Sub Structure Block Work to FFL |  |
|--|--|
| <b>Project:</b> Brooklands college, Weybridge            | <b>Date:</b> 01 November 2024                    |
| <b>Area:</b> Phase 1b                                    | <b>Am / Pm:</b> AM                               |
| <b>Locaton:</b> Plots 180-181                            | <b>Drawing Number:</b> SA00394-0150-A-SEMI1A-SUB |
| <b>Weather Condition:</b> Dry                            | <b>Sheet Number:</b> H                           |

Table of Contents

- Setting Out Line & Level to Current Drawings
- Product Material Compliant With Engineers/Architect Specification
- Specified Bedding Depth, Colour & Mlxing Ratio to Specification
- Specified DPC Installed & at Correct Level
- Specified Wall Ties & Air Vents Installed at Correct Location & Height
- DPC / Membrane Installed as Per Specification
- Brick Type
- Lintel Bearing

Completed By: James Brydon

Date Completed: 01 November 2024



**Completed By:** James Brydon

**Date Completed:** 01 November 2024



**Completed By:** James Brydon

**Date Completed:** 01 November 2024



Specified DPC Installed & at Correct Level

**Completed By:** James Brydon

**Date Completed:** 01 November 2024

Completed By: James Brydon



Date Completed: 01 November 2024



**Completed By:** James Brydon  
**Date Completed:** 01 November 2024

Completed By: James Brydon

Date Completed: 01 November 2024





Completed By: James Brydon

Date Completed: 01 November 2024



Proceed/not proceed

Reason for Rejection/Comments: Proceed to drainage

Signed for HOULIHAN: James Brydon

Date: 2024-11-01

Signed for client by:

Date:

The above inspections have been carried out and are acceptable/unacceptable

Non Conformities/Comments

Reason for non Conformities/Comments: na

Signed for HOULIHAN: James Brydon

Date: 2024-11-01

Signed for client by:

Date: