


Pre-Inspection Checklist Sub Structure Block Work to FFL	
Project: Brooklands college, Weybridge	Date: 05 December 2024
Area: Phase 1b	Am / Pm: AM
Locaton: Plots 182 -183	Drawing Number: SA00394-0150-A-SEMI1A-SUB
Weather Condition: Dry	Sheet Number: H

Table of Contents

- Setting Out Line & Level to Current Drawings
- Product Material Compliant With Engineers/Architect Specification
- Specified Bedding Depth, Colour & Mlxing Ratio to Specification
- Specified DPC Installed & at Correct Level
- Specified Wall Ties & Air Vents Installed at Correct Location & Height
- DPC / Membrane Installed as Per Specification
- Brick Type
- Lintel Bearing

Completed By: James Brydon

Date Completed: 05 December 2024



Completed By: James Brydon

Date Completed: 05 December 2024



Completed By: James Brydon

Date Completed: 05 December 2024



Specified DPC Installed & at Correct Level

Completed By: James Brydon

Date Completed: 05 December 2024

Completed By: James Brydon

Date Completed: 05 December 2024



DPC / Membrane Installed as Per Specification

Completed By: James Brydon
Date Completed: 05 December 2024

Completed By: James Brydon

Date Completed: 05 December 2024

External Materials Schedule - Dec 24									
Ref	Item	Code	Quantity	Unit	Material	Notes	Finish	Color	Notes
10	101	101001	100	m ²	Brickwork	Brickwork	Brickwork	Brickwork	Brickwork
10	102	101002	100	m ²	Brickwork	Brickwork	Brickwork	Brickwork	Brickwork
10	103	101003	100	m ²	Brickwork	Brickwork	Brickwork	Brickwork	Brickwork
10	104	101004	100	m ²	Brickwork	Brickwork	Brickwork	Brickwork	Brickwork
10	105	101005	100	m ²	Brickwork	Brickwork	Brickwork	Brickwork	Brickwork
10	106	101006	100	m ²	Brickwork	Brickwork	Brickwork	Brickwork	Brickwork
10	107	101007	100	m ²	Brickwork	Brickwork	Brickwork	Brickwork	Brickwork
10	108	101008	100	m ²	Brickwork	Brickwork	Brickwork	Brickwork	Brickwork
10	109	101009	100	m ²	Brickwork	Brickwork	Brickwork	Brickwork	Brickwork
10	110	101010	100	m ²	Brickwork	Brickwork	Brickwork	Brickwork	Brickwork
10	111	101011	100	m ²	Brickwork	Brickwork	Brickwork	Brickwork	Brickwork
10	112	101012	100	m ²	Brickwork	Brickwork	Brickwork	Brickwork	Brickwork
10	113	101013	100	m ²	Brickwork	Brickwork	Brickwork	Brickwork	Brickwork
10	114	101014	100	m ²	Brickwork	Brickwork	Brickwork	Brickwork	Brickwork
10	115	101015	100	m ²	Brickwork	Brickwork	Brickwork	Brickwork	Brickwork
10	116	101016	100	m ²	Brickwork	Brickwork	Brickwork	Brickwork	Brickwork
10	117	101017	100	m ²	Brickwork	Brickwork	Brickwork	Brickwork	Brickwork
10	118	101018	100	m ²	Brickwork	Brickwork	Brickwork	Brickwork	Brickwork
10	119	101019	100	m ²	Brickwork	Brickwork	Brickwork	Brickwork	Brickwork
10	120	101020	100	m ²	Brickwork	Brickwork	Brickwork	Brickwork	Brickwork

Completed By: James Brydon

Date Completed: 05 December 2024



Proceed/not proceed

Reason for Rejection/Comments: na

Signed for HOULIHAN: James Brydon

Date: 2024-12-05

Signed for client by:

Date:

The above inspections have been carried out and are acceptable/unacceptable

Non Conformities/Comments

Reason for non Conformities/Comments: na

Signed for HOULIHAN: James Brydon

Date: 2024-12-05

Signed for client by:

Date: