


Pre-Inspection Checklist	
Project: Brooklands college, Weybridge	Date: 04 February 2025
Area: Phase 1b	Am / Pm: AM
Locaton: Plots 180-181	Drawing Number: SA00394-0150-A-SEMI1A-SUB
Weather Condition: Dry	Sheet Number: H

Table of Contents

- Setting Out / Cross Check With Arch Plans
- Bedding
- Pipes
- Testing Priot to Covering (air or water)
- Backfilling / Casting In
- Incoming Services

Completed By: James Brydon

Date Completed: 04 February 2025



Bedding

Completed By: James Brydon

Date Completed: 04 February 2025



Completed By: James Brydon

Date Completed: 04 February 2025

material -> Osma

level / fill -> As dug

rocker lengths -> 550mm

lintel clearance -> Minimum 50mm



Testing Priot to Covering (air or water)

Completed By: James Brydon
Date Completed: 04 February 2025

Completed By: James Brydon

Date Completed: 04 February 2025

Material Used -> As dug

Plant Used -> Excavator



Completed By: James Brydon

Date Completed: 04 February 2025

Cross Check With Arch for Setting Out -> Yes

Correct ducting used -> Yes

EVCP's -> N/A

Incoming water services to follow guidelines as per NHBC -> Yes



Proceed/not proceed

Reason for Rejection/Comments: na

Signed for HOULIHAN: James Brydon

Date: 2025-02-04

Signed for client by:

Date:

The above inspections have been carried out and are acceptable/unacceptable

Non Conformities/Comments

Reason for non Conformities/Comments: na

Signed for HOULIHAN: James Brydon

Date: 2025-02-04

Signed for client by:

Date: